

BigLift Shipping B.V.

Customer Needs:

A high corrosion and abrasion resistant coating system. Easy to repair and to maintain while at Sea.

The Problem:

On board of the MV-Tramper, the ballast tanks are heavy corroded, dry docking to correct the problem is not an option at that time

The solution:

After cleaning the surfaces using handtool acc. to St.2 - St.3, the treated areas were coated to full satisfaction with a Unica System.

1. Primer	Uni-Micazinc MC Grey	DFT 75 µm
2. Intermediate	Uni-Protector MC	DFT 100 µm
3. Topcoat	Uni-Protector MC	DFT 100 µm

Now the Unica Coatings are used as maintenance system

